




VALUE OF ALL CAPACITORS ARE MMF UNLESS OTHERWISE SPECIFIED.
SWITCH S2 SHOWN IN RADIO POSITION.



TOUBLE SHOOTING NOTE

A gassy 12SA7 or 12SK7 may cause poor A.V.C. action thereby overloading the R.F. circuits and causing audio distortion at any setting of the volume control.

GENERAL ELECTRIC
MODEL 741
RADIO-PHONOGRAPH