



STROMBERG-CARLSON NO. 1100 AC-DC RADIO RECEIVERS



1100 RECEIVER—CHANGE IN RECTIFIER CIRCUIT

Field Coil of Speaker has been removed from negative side of Rectifier Circuit to positive side.

CIRCUIT BEFORE CHANGE
Using Capacitor 34506 C-1, C-2



CIRCUIT AFTER CHANGE
Using Capacitor 111001 C-1, C-2

