Radio-Phonograph Model 42-1002, Codes 121-122; PHILCO



RECTIFIER CIRCUIT—MODEL 42-1002, CODE 122







DRIVE CORD INSTALLATION