




Crosley Corp. Model 46FA, 46FB


SOCKET VOLTAGE CHART

NOTES:-

1. THESE ARE BOTTOM VIEWS OF SOCKETS.
2. MEASURE VOLTAGES FROM SOCKET LUGS TO CHASSIS (-B, -A, GROUND).
3. THESE VOLTAGES MEASURED USING AN ELECTRONIC VOLTMETER.
4. W. J. - WIRING JUNCTION.
5. NC - NO CONNECTION.
6. SOCKET VOLTAGE TOLERANCE, 10%.



The material presented on this page has been prepared by and is printed through the courtesy of THE CROSLY CORP.



SCHMATIC DIAGRAM— MODELS 46FA and 46FB