


MASCO PORTABLE PHONOGRAPH AMPLIFIER

MARK SIMPSON MANUFACTURING CO., INC.



WHEN AMPLIFIER DOES NOT PLAY:

1. SEE THAT ALL TUBES ARE INSERTED IN CORRECT SOCKETS.
2. CHECK ALL CONNECTIONS.
3. CHECK FILTER CONDENSER FOR OPEN OR SHORT.
4. CHECK LINE CORD FOR OPEN CIRCUIT.
5. TEST 125 OHM 10 WATT WIRE WOUND RESISTOR FOR OPEN CIRCUIT.

NOTE: WHEN 35A5 IS USED, 125 OHM 10 WATT RESISTOR IS REPLACED BY 200 OHM 10 WATT RESISTOR.

WHEN ASTATIC RL-267 PICKUP IS USED A .1 MFD. CONDENSER IS CONNECTED ACROSS THE 14H7 CATHODE RESISTOR.