



BOTTOM VIEW
 The coil assembly is shown midway between the 1.3-2.8 mc. and 2.7-6.4 mc. ranges.

NATIONAL COMPANY, INC.

THE NC-100A RECEIVER

