



MARELLI - AP 20 M

- | | |
|-------------------|-------------|
| R1-R2-R11 | 0,2 Mohm |
| R3 | 15 kohm |
| R4-R8-
R12-R15 | 1,6 kohm |
| R5 | 0,1 Mohm |
| R6 | 0,63 Mohm |
| R7 | 50 kohm |
| R9 | 1 Mohm |
| R10 | 0,5 Mohm |
| R14-R16 | 0,1 Mohm |
| R17-R18 | 0,64 Mohm |
| R19-R20 | 0,32 Mohm |
| R21-R22 | 1 kohm |
| R23 | 160 ohm |
| R24 | 7 kohm |
| R25 | 40 kohm |
| R26 | 2 kohm |
| R27 | 32 kohm |
| R28-R29 | 0,1 Mohm |
| R30-R31 | 0,2 Mohm |
| C1 | 0,5 μ F |
| C2-C5 | 50.000 pF |
| C3 | 5 000 pF |
| C4 | 4.000 pF |
| C6 | 100 pF |
| C8-C9 | 32 000 pF |
| C11-C12 | 64 μ F |
| C13 | 32 μ F |
| C15 | 10.000 pF |

C7-C10 C14 25+100+25 μ F

CAMBIO TENSIONE

PRESA ALTOP

PRESA ALIMEN