



C 1 - C 2	16+16 pF
C 3 - C 4	32+32 »
C 5 - C 6	16+16 »
C 7	16+16 »
C 8	16+16 »
C 9	16.000 pF
C 10	0.1 pF
C 11	0.1 »
C 12	0.1 »
C 13	0.1 »
C 14	10.000 pF

  

R 1	0,1 M
R 2	0,4 M
R 3	1000
R 4	1 M
R 5	50.000
R 6	0,1 M
R 7	500
R 8	0,1 M
R 9	1000
R 10	0,1 M
R 11	0,1 M
R 12	6400
R 13	0,25 M
R 14	0,25 M
R 15	130
R 16	15.000
R 17	10.000
R 18	0,5 M
R 19	3200
R 20	50
R 21	50
R 22	50
R 23	50