


SPECIFICATIONS: NOTE ①

LOAD Z	LOW PASS	CROSS OVER	HIGH PASS	ATTENUATION

CIRCUIT:



NOTES:

- ① USE STANDARD TEST FIXTURE
- ② NIP TO (1000) (1000) (1000)
- ③ AIR CORE INDUCTOR