

JBL Repair Kit Goes Into List

NOTES	REPAIR KIT	KIT GOES INTO/NOTES
	C8RMI10	MI-10, MI-10-1
	C8RMI12	MI-12
	C8RMI12-1	MI-12-1
	C8RMI15A	MI-15A
	CRPR8	LE8-7, PR8
	CRPR10	PR7, PR10
N/A	(CRPR10F)	*FSO*, PR10F (Similar to K110)
N/A	(CRPR14)	*FSO*, PR14
	CRPR15C	PR15C, PR15D
	CRPR300	PR300
	C8RLE52	LE5-2
D	(C8RLE55)	Replaced by C8RLE59
D	(C8RLE56)	Replaced by C8RLE510
	C8RLE59	LE5H, LE5-3!, LE5-5!, LE5-9!, 2105!, 2105H!, 2105H, LE5-11
	C8RLE510	LE5-6!, LE5-8!, LE5-10, LE5-12
	C8RLT-1	LT-1, SLT-1
	C8RLE8T	LE8, LE8-1, LE8T, LE8T-H, LE8-101
	C8RLE10A	LE10A, LE10B!, LE10, LE10-101
	C8RLE10H-1	LE10H-1
	C8RLE14A	LE14A, LE14H, 5A390, 401-134!, LE14-1
N/A	(C8RE14A2)	*FSO*, LE14A-2
	C8RLC14CLF	LC14C, LE14C, 5A395
	C8RLE14H-1	LE14H-1
	C4RA15	A15G
	C8RLE15B	LE15B, 2216
	C8RLE15H	LE15H, 2215H
D	(C16RD15S)	Replaced by C16RE130
	D8RLE20	LE20, LE20-1, 401-132!
	D4R024	024
	D8RLE25	LE21H, LE25, LE25-1
	D8RLE252	LE25-2, LE25-3
	D8RLE254	LE25-4, LE25-5

NOTES:

D - Recently discontinued, use indicated replacement.

N/A - *FSO*, Not available, return to JBL "FACTORY SERVICE ONLY."

! - Closest substitute available, original assemble not produced.

JBL Repair Kit Goes Into List

NOTES	REPAIR KIT	KIT GOES INTO/NOTES
	D8RLE26	LE26
	C4RA30	A30G
	D8R033	033
	D8R034	034
	D8R035TI	035TI
D	(C4M35)	M35-4, 70777022, Replaced by C4RE130
	D8R044	044
	D8R044-1	044-1
	D8R044TI	044TI, 044TI-1
	D8R066	066
	D8R075	075, 075R, 2402, 2402H, 075-022!, 075-105!, 075-105B!, 075-105C!, 075-105CH!, 075-105D, 2404H-1
	D8R076	076, 2403, 2403H
	C8R108	108H
	C4RK110	M11-4, K110-4
	C8RK110	M10, M11, M12-8, D110F, E110-8, K110, 2120, 043109, 043109-A, 043109H
	C16RK110	M11-6, M12-6, D110F-6, E110-16, K110-16
	C8RLE111A	LE111A
	C8RLE111H	LE10H, LE111H
	C8R112A	112A, 112H, 2108H
	C8R115	115H
	C8R115H-1	115H-1
	C8R116A	116A, 116H
	C8R116H-2	116AH-2
	C8R117	117H, 117H-1
	C8R118	118H
	C8RE120	M20, M21, M22-8, D120, D120F, E120-8, K120, D131!, D131F, 2130, 092577, 092577-A, 092577H
	C16RE120	M21-16, M22-16, D120F-6, E120-16, K120-16, 023125-A, 123125J
	C4RK120	M21-4, D120F-2, K120-4
D	(C8RK120)	Replaced by C8RE120
D	(C16RK120)	Replaced by C16RE120

NOTES:

D - Recently discontinued, use indicated replacement.

N/A - *FSO*, Not available, return to JBL "FACTORY SERVICE ONLY."

! - Closest substitute available, original assemble not produced.

JBL Repair Kit Goes Into List

NOTES	REPAIR KIT	KIT GOES INTO/NOTES
	C8R121A	121A, 121H
D	(C8R122A)	Replaced by C8R129H
D	(C8R122A1)	Replaced by C8R129H
N/A	(C8R123A2)	*FSO*, 123A-2
	C8RD1233	D123-3
N/A	(C8RD124R)	*FSO*, D124R
D	(C8R125A)	Replaced by C8R127A
	C8RG125-8	G125-8, G125A-8
	C8R126A	126A
	C8R127A	125A, 127A, 127H
	C8R127H-1	127H-1
	C8R128H	128H
	C8R128H-1	128H-1
	C8R129H	122A!, 122A-1!, 129H
D	(C8RD130)	Replaced by C8RE130
	C4RE130	M31-4, M32-4, M35-4!, D130F-2, E130-4, K130-4, 70777022!
	C8RE130	M30, M31, M32-8, D130!, D130F, D130H!, E130-8, K130, 2135 023101, 023101-A, 023101H
	C16RE130	D15S!, M31-16, M32-16, D130F-6, E130-16, L130-16, 970302-A
D	(C4RL130)	Replaced by C4RE130
D	(C8RK130)	Replaced by C8RE130
D	(C16K130)	Replaced by C16RE130
D	(C8RD131)	Replaced by C8RE120
	C8RG135	G135-8
	C8RG135A	G135A-8
	C16R136B	136B
D	(C8RD140R)	Replace with C8R2205 AND 21514 dome
	C8RE140	M40, M41, M42-8, D140F, E140-8, K140, 043091, 043091-A, 043091H, 970401!, D140R
	C16RE140	M41-16, M42-16, D140F-6, E140-16, K140-16, 970402, 970402-A!
	C4RK140	M41-4, D140F-2, K140-4, 970401-A
D	(C8RK140)	Replaced by C8RE140

NOTES:

D - Recently discontinued, use indicated replacement.

N/A - *FSO*, Not available, return to JBL "FACTORY SERVICE ONLY."

! - Closest substitute available, original assemble not produced.

JBL Repair Kit Goes Into List

NOTES	REPAIR KIT	KIT GOES INTO/NOTES
D	(C16RK140)	Replaced by C16RE140
	C8RE145	M46-8, E145-8, 150-4H
	C16RE145	M46-16, E145-16
D	(C4RK145)	Replaced by C8RK145 OR C16RK145
	C8RK145	M45, K145, M45-4, K145-4
	C16RK145	M45-6, K145-16
	C16R1504C	150-4!, 150-4C
	C4RK151	M51-4, K151-4
	C8RK151	K151, K151-16!
D	(C8RE151)	Replaced by C8RE155
	C8RE155	M55-8, E151-8, E155-8
N/A	(C8RD260)	*FSO*, D260, AMPEX 8
D	(C8RD280)	Replaced by C8R2110 OR C8RD208
	C4R303G-2	303G, 303G-1, 303G-2
	C4R305G-1	305G, 305G-1
	C4R305G-2	305G-2
	C4R306G-2	306G-2
	C4R308G-1	308G, 308G-1
	C4R308G-2	308G-2
	C4R310G-1	310G, 310G-1
	C4R310G-2	310G-2
	C4R312G	312G, 312G-1
	D16R375AB	375AB, 375EX, 375FH, 375HP, 5P360, MI11426, MI11426A
	C8R2108	2108
	C8R2110	D204!, D208, D208H, D216!, D280!, 2110, 2110H
	C8R2115	LE8T-2, 2115A, 2115H
	C16R2115	LE8TX, 2115, 2115B, 2115J
	C8R2118	2118H
	C16R2118	2118J, 2118J-1
	C8R2121	2121, 2121H
	C8R2122H	2122H
	C8R2123H	2123H

NOTES:

D - Recently discontinued, use indicated replacement.

N/A - *FSO*, Not available, return to JBL "FACTORY SERVICE ONLY."

! - Closest substitute available, original assemble not produced.

JBL Repair Kit Goes Into List

NOTES	REPAIR KIT	KIT GOES INTO/NOTES
	C8R2125	D123, 2125, D123F
	C8R2145LF	LE12C, 2145
	C8R2145ALF	LE12C-1, 2145A
	D8R2145HF	LE12C, LE12C-1, LE14C, 2145, 2145A, 5A395
	C8R2150LF	2150, 5A415
N/A	(C8R2150HF)	*FSO*, 2150, 5A415
	C8R2202	2202A, 2202H
	C16R2202	2202B, 2202J
	C8R2203	124A, 124H, 2203A, 2203H
D	(C8R2205)	2205A, 2205H, Replaced by C8R2225
D	(C16R22205)	2205B, 2205J, Replaced by C16R2225
D	(C32R2205)	Replaced by C8R2225 or C16R2225
	C8R2212	123A, 123A-1, 2212, 401-133!
	C8R2213	123A-3, 2213, 2213H
	C8R2214	2214H
	C8R2215	2215A
	C16R2215	LE15A, 150-H (Very old), 2215, 2215B
D	(C8R2216)	Replaced by C8RLE15B, C8R2215
	C8R2220	130A, 130AS!, 130H, 2220A, 2220C!, 2220H
	C16R2220	130B, 130BP, 2220B, 2220C!, 2220J
D	(C32R2220)	2220C, Replaced by C8R2220 PR C16R2220
	C8R2225	2205A, 2205C!, 2205H, 2225H
	C16R2225	2205B, 2205C!, 2205J, 2225J
D	(C8R2230)	Replaced by C8R2235 (Visual change)
D	(C8R2231)	Replaced by C8R2235
D	(C8R2234)	Replaced by C8R2235 (Don't use mass ring with kit)
	C8R2235	135A!, 136A!, 136H!, 2230A!, 2231A!, 2231H!, 2234H, 2235H
	C4R2240	2240G
	C8R2240H	2240H
	C8R2245H	2245H
	CR2290	PR15, PR15E, PR15F, PR15R, 2290
N/A	(CR2295)	*FSO*, PR12, 2295

NOTES:

D - Recently discontinued, use indicated replacement.

N/A - *FSO*, Not available, return to JBL "FACTORY SERVICE ONLY."

! - Closest substitute available, original assemble not produced.

JBL Repair Kit Goes Into List

NOTES	REPAIR KIT	KIT GOES INTO/NOTES
	D16R2405	077, 2405, 2405H, 2404H
	D16R2410	LE75, D174, LE175, LE175-200, LE175DLH, 2410, 5A350, MI11419
	D8R2415	2415H
	D8R2416	2416H
	D16R2420)	Replaced by D16R2421
	D8R2421	2421A
	D16R2421	LE85!, 275!, 2420!, 5A355!, 2421B
	D8R2425	LE85!, 2470!, 2421!, 2420!, 2425H,, 2426H, 2427H
	D16R2425	LE85!, 2470!, 2421!, 2420!, 2425J, 2426, J2427H
	D16R2440	375, 375H, 2440, 5A360, MI11427
	D16R2441	2445J, 2441, 2440, 375, 375H, 376
	D16R2445	2445J, 2441, 2440, 375, 375H, 376
	D16R2460	LE100S, LE175HP, 2460, 5P350
	D16R2470	2461, 5P355, 2470
D	(D16R2480)	Replaced by D16R2482
	D16R2482	2480, 2482, 2485

NOTES:

D - Recently discontinued, use indicated replacement.

N/A - *FSO*, Not available, return to JBL "FACTORY SERVICE ONLY."

! - Closest substitute available, original assemble not produced.